

**THIS IS A SAMPLE REPORT**

Vehicle Report valid as at: Thursday, 3 July 2014 3:40 pm

**Registration or VIN Provided: PR3945****Attention. Please read carefully.**

- ✓ This vehicle is **NOT** reported stolen.  
The current registered owner is: **THAMES MOBILITY VEHICLE INC**
- ⚠ This vehicle's registration is currently **OVERDUE**. The registration **EXPIRED 1 years, 6 months, 23 days ago on the 11/12/2012**.
- ⚠ The **WOF EXPIRED 2 years, 21 days ago on the 12/06/2012**.
- ⓘ This vehicle's recorded odometer values are **INCONSISTENT** - please check them carefully.  
This vehicle's Road User Charges are paid up to 81,146 km

**Vehicle Details:**

<b>Vehicle Year, Make &amp; Model:</b>	1990 CUSTOMBUILT DAF VH400ET Minibus	<b>Colour:</b>	WHITE
<b>Registration:</b>	PR3945	<b>CC Rating:</b>	2500
<b>VIN:</b>		<b>Plate History:</b>	<b>Plate:</b> <b>Date Issued:</b>
<b>Chassis Number:</b>	872435		PR3945      29/01/1991
<b>Engine Number:</b>	P158GA0034/C7		
<b>Fuel Type:</b>	Diesel		
<b>Last Odometer Reading:</b>	78000 km		
<b>Date of Last Odometer Reading:</b>	12/12/2011		
<b>Gross Vehicle Mass:</b>	3450 kg		
<b>Number of Seats:</b>	10		

**Registration & WOF Details:**

<b>Date First Registered in NZ:</b>	29/01/1991	<b>Last WOF Inspection:</b>	12/12/2011
<b>Licence Issue Date:</b>	12/12/2011	<b>Last WOF Inspection Result:</b>	Pass
<b>Licence Expiry Date:</b>	11/12/2012	<b>WOF Expiry Date:</b>	12/06/2012
<b>Subject to Warrant of Fitness:</b>	Yes		
<b>Subject to Certificate of Fitness:</b>	No		
<b>Subject to Road User Charges:</b>	Yes		

## Importation Details

**NZ New / Import:** This vehicle is NZ new.  
**Previous Country:** **Country of Origin:** United Kingdom  
**Imported Damaged:** No **Assembly Type:** Unknown

## Odometer Records


Odometer Source:	Odometer Value:	Date Recorded:
Warrant of Fitness Inspection	78,000 km	12/12/2011
Warrant of Fitness Inspection	76,854 km	04/10/2004
Warrant of Fitness Inspection	74,174 km	06/04/2004
Warrant of Fitness Inspection	72,451 km	07/10/2003
Warrant of Fitness Inspection	70,409 km	10/04/2003
Warrant of Fitness Inspection	69,241	19/09/2002
Warrant of Fitness Inspection	66,325	26/03/2002
Warrant of Fitness Inspection	65,858	04/10/2001
Warrant of Fitness Inspection	61,680	10/04/2001
Warrant of Fitness Inspection	59,852	25/10/2000
Warrant of Fitness Inspection	56,258	19/04/2000
Warrant of Fitness Inspection	53,470	19/10/1999
Warrant of Fitness Inspection	5,220 Inconsistent	19/04/1999
Warrant of Fitness Inspection	41,103	28/01/1998
Warrant of Fitness Inspection	35,455	15/11/1996
Warrant of Fitness Inspection	30,736	30/01/1996
Warrant of Fitness Inspection	25,831	13/01/1995

## Ownership History Records:

### Current Owner

**Name:** THAMES MOBILITY VEHICLE **Ownership Date:** 29/01/1991  
 INC **Ownership Duration:** 23 years, 5 months, 4 days  
**Address:** 3261 STATE HIGHWAY 6 **Ownership Status:** Complete  
 RD 1 7873 **Person or Organisation:** Company  
 RUNANGA  
**Postal Address:** 3261 STATE HIGHWAY 6  
 RD 1 7873  
 RUNANGA

## Fuel Saver, Emission, Fuel Economy & Safety Details:



The fuelsaver image must be printed to 196mm x 136mm for use in vehicle windows.

Please ask about our custom reports to receive this as a standard option, [or click here for a printable version.](#)

### Emission Details:

CO2 Rating: UNKNOWN  
☆☆☆☆☆☆

CO2 Emissions: UNKNOWN

Pollutants Rating: UNKNOWN  
☆☆☆☆☆☆

Test Regime: UNKNOWN

### Fuel Economy Details:

Fuel Consumption: UNKNOWN

Fuel Economy Rating: UNKNOWN  
☆☆☆☆☆☆

### Driver Safety Details:

Driver Safety Rating: UNKNOWN  
☆☆☆☆☆☆

Driver Safety Test: UNKNOWN

Thank you for using the AutoFinder Vehicle Details Service.

Personal Service from 8am to 5pm, Monday - Friday.

Phone: 0800 909 777 / 0900 55 007 or: [www.autofinder.co.nz](http://www.autofinder.co.nz)

**Disclaimer:** The information provided in the AutoFinder Vehicle Details Report has been compiled from records and information supplied by third party sources. This information is believed to be correct as at the date of the report. We have not audited the information and therefore neither we nor any of our employees, licensees or agents accept any responsibility for the accuracy of the material from which this report has been prepared. AutoFinder nor any of our employees, licensees or agents accept any liability for any loss or damage that may result from actions or failure to act upon information provided. Further neither we nor any of our employees, licensees or agents accept any responsibility on any ground whatsoever to any other person.

MotorMania NZ Ltd. t/a Autofinder

Telephone: 06 3555 007 Fax: 06 3535 007

PO Box 4019 Manawatu Mail Centre, Palmerston North 4442

**THIS IS A SAMPLE REPORT**